



**\*MACARTHUR MAZE/580 DECK COLLAPSE\***

**May 10, 2007**

Progress

- Heat straightening of girders continues on 880 connector.
- Heat straightening of girders on 580 begins.
- Repairs to columns on 880 connector completed.
- Repairs to columns on 580 connector continues. Concrete pour completed on both MB #19 columns.
- Removal of damaged bolts on 580 connector begins.
- Girder fabrication begins in Arizona.
- Red curb painted on West Grand Avenue between Market Street and Martin Luther King Boulevard for no parking zone. Placed 30 mile per hour signs for traffic control.